

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/12/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 11/5/2012 – 0700, 11/27/2012
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, TX
8. Activity Log			
Time	Major Events		
08:00	<ul style="list-style-type: none"> Internal Command and General Staff meeting 		
09:00	<ul style="list-style-type: none"> Boat safety meeting at C0.4 boat launch. Launch. MP5.20 LDB spontaneous sheen and tar globs observed. Ceresco Dam observed a crew surveying an anchor point for the bathymetry survey. MP5.5 Center channel observed sheen and tar globs. MP4.75 LDB sheen and tar globs observed. MP4.5 LDB boat agitated the sediment sheen and tar globs observed. MP15.0 sheen and tar globs observed in the river channel. MP15.0 RDB South Mill Pond sheen and tar globs observed. MP15.25 RDB South Mill Pond sheen and tar globs observed. MP14.75 LDB sheen and tar globs observed. Morrow Lake Delta Gate A observed the Bathymetry team. 		
16:00	Returned to Boat Launch C0.4. Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			